AECOM


SITE PHOTOGRAPH LOG

Project Name:		Project No.
Taylor Run Stream Restoration		60742359

Photo No.	Date:
1	07/24/25

Direction Photo Taken:
Upstream

Description:
72-inch outfall condition. Gully next to right wingwall (look upstream) and beginning of plunge pool (Project Area 1)



AECOM


SITE PHOTOGRAPH LOG

Project Name:		Project No.
Taylor Run Stream Restoration		60742359

Photo No.	Date:
2	07/24/25

Direction Photo Taken:
Right Bank

Description:
Left wingwall (looking upstream) condition. (Project Area 1)




SITE PHOTOGRAPH LOG

Project Name:		Project No.
Taylor Run Stream Restoration		60742359

Photo No.	Date:
3	07/24/25

Direction Photo Taken:
Downstream

Description:
Downstream condition of stream with concrete debris, unstable (soon to fall) trees, woody debris build up



SITE PHOTOGRAPH LOG

Project Name:		Project No.
Taylor Run Stream Restoration		60742359

Photo No.	Date:
4	07/24/25

Direction Photo Taken:
Left Bank

Description:
Concrete debris in the channel, downstream of Project Area 1



SITE PHOTOGRAPH LOG

Project Name:		Project No.
Taylor Run Stream Restoration		60742359

Photo No.	Date:
5	07/24/25

Direction Photo Taken:
Left Bank

Description:
Fallen trees causing debris build up in the channel. View from left bank. Between Project Area 1 and 2



SITE PHOTOGRAPH LOG

Project Name:		Project No.
Taylor Run Stream Restoration		60742359

Photo No.	Date:
6	07/24/25

Direction Photo Taken:
Downstream

Description:
Concrete debris in the channel, fallen trees, bank erosion and woody debris build up in channel between Project Area 1 and 2




SITE PHOTOGRAPH LOG

Project Name:		Project No.
Taylor Run Stream Restoration		60742359

Photo No.	Date:
7	07/24/25

Direction Photo Taken:
Left Bank

Description:
Eroding channel bank between Project Area 1 and 2



SITE PHOTOGRAPH LOG

Project Name:		Project No.
Taylor Run Stream Restoration		60742359

Photo No.	Date:
8	07/24/25

Direction Photo Taken:
Downstream

Description:
Falling trees and debris build up in the stream between Project Area 1 and 2




SITE PHOTOGRAPH LOG

Project Name:		Project No.
Taylor Run Stream Restoration		60742359

Photo No.	Date:
9	07/24/25

Direction Photo Taken:
Left Bank

Description:
36-inch outfall showing undercut of headwall and erosion of the left side




SITE PHOTOGRAPH LOG

Project Name:		Project No.
Taylor Run Stream Restoration		60742359

Photo No.	Date:
10	07/24/25

Direction Photo Taken:
Downstream

Description:
Exposed sanitary sewer pipe next to 36-inch outfall (Project Area 2)



AECOM


SITE PHOTOGRAPH LOG

Project Name:		Project No.
Taylor Run Stream Restoration		60742359

Photo No.	Date:
11	07/24/25

Direction Photo Taken:
Left Bank

Description:
Severe bank erosion immediately downstream from the 36-inch outfall (Project Area 2)



AECOM


SITE PHOTOGRAPH LOG

Project Name:		Project No.
Taylor Run Stream Restoration		60742359

Photo No.	Date:
12	07/24/25

Direction Photo Taken:
Upstream

Description:
Upstream stream condition, standing at the 36-inch outfall. Fallen tree(s) due to bank instability (Project Area 2)




SITE PHOTOGRAPH LOG

Project Name:		Project No.
Taylor Run Stream Restoration		60742359

Photo No.	Date:
13	07/24/25

Direction Photo Taken:
Upstream/Right Bank

Description:
Exposed sanitary sewer manhole with undercut of concrete skirt




SITE PHOTOGRAPH LOG

Project Name:		Project No.
Taylor Run Stream Restoration		60742359

Photo No.	Date:
14	07/24/25

Direction Photo Taken:
Downstream

Description:
Upstream stream condition from exposed sanitary sewer manhole (Project Area 3)



AECOM


SITE PHOTOGRAPH LOG

Project Name:		Project No.
Taylor Run Stream Restoration		60742359

Photo No.	Date:
15	07/24/25

Direction Photo Taken:
Downstream

Description:
Downstream conditions of the exposed sanitary sewer manhole. Woody Debris build up in the back. (Project Area 3)



AECOM

SITE PHOTOGRAPH LOG

Project Name:		Project No.
Taylor Run Stream Restoration		60742359

Photo No.	Date:
16	07/24/25

Direction Photo Taken:
Upstream

Description:
Woody debris build up between Project Area 3 and Project Area 4. Falling trees from bank instalbility



AECOM

SITE PHOTOGRAPH LOG

Project Name:		Project No.
Taylor Run Stream Restoration		60742359

Photo No.	Date:
17	07/24/25

Direction Photo Taken:
Left Bank

Description:
Exposed root exposure of champion tree (Project Area 4)



AECOM


SITE PHOTOGRAPH LOG

Project Name:		Project No.
Taylor Run Stream Restoration		60742359

Photo No.	Date:
18	07/24/25

Direction Photo Taken:
Upstream/Left Bank

Description:
Horizontal extent of root exposure of the champion tree (Project Area 4)



SITE PHOTOGRAPH LOG

Project Name:		Project No.
Taylor Run Stream Restoration		60742359

Photo No.	Date:
19	07/24/25

Direction Photo Taken:
Downstream/Left Bank

Description:
Leaning sheet pile wall and build of debris within the channel (Project Area 4)




SITE PHOTOGRAPH LOG

Project Name:		Project No.
Taylor Run Stream Restoration		60742359

Photo No.	Date:
20	07/24/25

Direction Photo Taken:
Downstream

Description:
Exposed sanitary sewer pipe near sheet pile wall (Project Area 4)



SITE PHOTOGRAPH LOG

Project Name:		Project No.
Taylor Run Stream Restoration		60742359

Photo No.	Date:
21	07/24/25

Direction Photo Taken:
Upstream Left Bank

Description:
Exposed roots, stream bank erosion and gully formed from trail side runoff




SITE PHOTOGRAPH LOG

Project Name:		Project No.
Taylor Run Stream Restoration		60742359

Photo No.	Date:
22	07/24/25

Direction Photo Taken:
Upstream

Description:
Condition of right bank, downstream of study extent



SITE PHOTOGRAPH LOG

Project Name:		Project No.
Taylor Run Stream Restoration		60742359

Photo No.	Date:
23	07/24/25

Direction Photo Taken:
Downstream

Description:
Condition of the stream downstream of study extent




SITE PHOTOGRAPH LOG

Project Name:		Project No.
Taylor Run Stream Restoration		60742359

Photo No.	Date:
24	10/08/25

Direction Photo Taken:
Right Bank

Description:
From center of sanitary manhole it is 2 feet from the sheet pile wall



SITE PHOTOGRAPH LOG

Project Name:		Project No.
Taylor Run Stream Restoration		60742359

Photo No.	Date:
25	10/08/25

Direction Photo Taken:
Downstream

Description:
Outer extent of sanitary sewer manhole is 10 inches from the sheet pile wall



SITE PHOTOGRAPH LOG

Project Name:		Project No.
Taylor Run Stream Restoration		60742359

Photo No.	Date:
26	10/08/25

Direction Photo Taken:
Right Bank

Description:

Sanitary Sewer manhole is 19 feet from the start of the sheet pile wall

