
## KING & COMMONWEALTH STREETSCAPE IMPROVEMENTS



## Highlights from Complete Streets Repaving Feedback

- Need better crosswalks and visibility at crosswalks (flashing beacons, lights)
- Curb cuts are too steep
- Increased signage and pavement markings for pedestrians at King Street Metro
- Protected bike lanes
- More signage
- Too much cut through traffic
- Speed humps are too high
- More speed humps are needed
- Cars move into bicycle lanes to avoid speed humps
- Need better lane markings
- Intersection of Cameron and Commonwealth is difficult to navigate; cars run stop sign





For more information, visit the project website at ALEXANDRIAVA.GOV/GO/4899