

**Potomac River Generating
Station Pictures**
August 31, 2007



Equipment staged in northwest parking lot.



Equipment staged in northwest parking lot.



Equipment staged in northwest parking lot.



View of scaffolding and equipment staged on the northern fence line of the facility.



Equipment staged on the northern fence line of the facility.



Equipment staged on the northern fence line of the facility.



Contractor trailers staged at the northern end of the plant.



Ductwork staged along the northern fence line of the facility.



Large crane (not in use at the time of the site visit) staged on the northeast side of the plant.



Structural beams and stairways removed near base of Stack #2.



View at base of stacks.



View of scaffolding erected around stacks and ductwork of Stack #4.



Work observed around Stack #4.



Another view of scaffolding set up around duct work near Stack #4.



Equipment staged at the base of Stack #4 and #5.